BOREWELL COMPLETION REPORT

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore - 560 094
Mobile : +91 9342202932 | 9343202932

No. : 785 Date : 10-09-2020

1. Customer's Name and Address : Assistant Executive Engineer
   With Telephone No. Vidyaranyapura Sub Division
   BBMP, Bangalore-97
2. Well Location : Indian Express layout Main Road
3. Total Well Depth / Drilled in Ft. : 1168 FT
4. Casing Erected in Ft. : 80 FT
5. Water Struck at the Depth of : 890 FT
6. Total Yield (Measuring method "V" North 2'6" / inches on " V" North)
7. Formation of Soil / Well Water Condition : clear
   Boulders / Silt / Loose Soil / Clear clear
8. At the Depth of : 890 FT
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good / satisfied / Party agreed conditions.

Once the well handed over to party, Company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

Assistant Executive Engineer
Vidyaranyapura Sub Division

I Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Manager / Proprietor

VINAYAKA ENTERPRISES

BOREWELL COMPLETION REPORT

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore - 560 094
Mobile : +91 9342202932 | 9343202932

No. 784 Date : 10-09-2020

1. Customer's Name and Address : Assistant Executive Engineer
   With Telephone No. Vidyaranyapura Sub Division
   BBMP, Bangalore-97
2. Well Location : Lake Near Gorelen, Thindlu Pooja Station
3. Total Well Depth / Drilled in Ft. : 1152 FT
4. Casing Erected in Ft. : 220 FT
5. Water Struck at the Depth of : 860 FT
6. Total Yield (Measuring method "V" North 2'0" / inches on " V" North)
7. Formation of Soil / Well Water Condition : clear
   Boulders / Silt / Loose Soil / Clear clear
8. At the Depth of : 860 FT
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good / satisfied / Party agreed conditions.

Once the well handed over to party, Company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

Assistant Executive Engineer
Vidyaranyapura Sub Division

I Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

~~Manager~~ / Proprietor

BOREWELL COMPLETION REPORT

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore - 560 094
Mobile : +91 9342202932 | 9343202932

No. 781

Date : 25-08-2020

1. Customer's Name and Address : Assistant Executive Engineer
   With Telephone No. Vidyaranyapura Sub Division
   BBMP. Bangalore
2. Well Location : Munimuniappa layout main Road
3. Total Well Depth / Drilled in Ft. : 1165 Ft
4. Casing Erected in Ft. : 273 Ft
5. Water Struck at the Depth of : 965 Ft
6. Total Yield (Measuring method "V" North 3'0" / inches on " V" North)
7. Formation of Soil / Well Water Condition : clear lime
   Boulders / Silt / Loose Soil / Clear clear
8. At the Depth of : 965 Ft
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good / satisfied / Party agreed conditions.

Once the well handed over to party, Company is no way responsible for further developments if anything in the well or what so ever.

Assistant Executive Engineer
Vidyaranyapura Sub Division

Party's Signature

I Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Manager / Proprietor

BOREWELL COMPLETION REPORT

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore - 560 094
Mobile : +91 9342202932 | 9343202932

No. 782 Date : 18-08-2020

1. Customer's Name and Address : Assistant Executive Engineer
   With Telephone No. Vidyaranyapura Sub Division
   BBMP, Bangalore.
2. Well Location : Bullet Drilling Layout 1st Main
3. Total Well Depth / Drilled in Ft. : 1155 FT
4. Casing Erected in Ft. : 269 FT
5. Water Struck at the Depth of : 950 FT
6. Total Yield (Measuring method "V" North 2'5" / inches on " V" North)
7. Formation of Soil / Well Water Condition : clear
   Boulders / Silt / Loose Soil / Clear clear
8. At the Depth of : 950 FT
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump ✓

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good / satisfied / Party agreed conditions.

Once the well handed over to party, Company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

Assistant Executive Engineer
Vidyaranyapura Sub Division

I Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Manager / Proprietor